



CONFIDENTIAL



# NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER **RECONSTRUCTION ACTIVITY** **THERMAL ELECTRIC POWERPLANTS** **NORTH VIETNAM**

25X1



25X1

25X1



25X1

25X1  
 25X1

**CONFIDENTIAL**

25X1

## (c) NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER

Attachment to N. 1775  
8 September 1969

Page 1 of 2

## REFERENCE:

RECONSTRUCTION ACTIVITY AT THERMAL ELECTRIC  
POWERPLANTS,  
NORTH VIETNAM

25X1

1. SIGNIFICANCE:

THIS BOARD DEPICTS THE REPAIR OF THE ONE  
REMAINING THERMAL ELECTRIC POWERPLANT (TPP)  
CAPABLE OF BEING RESTORED IN NORTH VIETNAM, AND  
THE FIRST EVIDENCE OF MAJOR EXTERNAL REPAIR AT ANY  
TPP.

2. LOCATION:

NAM DINH, NORTH VIETNAM. BEN THUY, NORTH VIETNAM,  
LOCATED 3 NM SE OF VINH

3. REMARKS:

SINCE THE BOMBING OF NORTH VIETNAM WAS HALTED, ALL  
OF THE PREVIOUSLY DAMAGED TPP HAVE APPARENTLY BEEN  
RESTORED TO AT LEAST PART OF THEIR ORIGINAL PRO-  
DUCTION CAPABILITY. OF A TOTAL OF 17 PLANTS, FOUR  
WERE UNTOUCHED AND 13 WERE STRUCK. CURRENTLY, 10  
OF THE STRUCK PLANTS HAVE BEEN RESTORED TO  
OPERATION WITH THE REMAINING THREE PLANTS ALMOST  
TOTALLY DESTROYED AND NO RECONSTRUCTION ATTEMPTS  
OBSERVED.

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing boards (s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue. For information concerning these notes contact Chief, Imagery Exploitation Group NPIC.

GROUP 1 EXCLUDED FROM  
AUTOMATIC DOWNGRADING  
AND DECLASSIFICATION

**CONFIDENTIAL**

25X1

**CONFIDENTIAL**

25X1

(c) NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER

Attachment to N-1775  
8 September 1969

Page 2 of 2

4. MISSION READOUT: [REDACTED] HAS CONFIRMED THE RESUMPTION OF OPERATIONS AT THE BEN THUY TPP. A NEW COAL PROCESSING SHED, COAL PILES, REPAIRS TO THE FLUE, AND THE ADDITION OF A NEWLY CONSTRUCTED WATER/WASTE DISPOSAL SYSTEM ARE EVIDENT. SMOKE IS OBSERVED EMANATING FROM THE TERMINUS OF THE FULE, CONFIRMING THAT THE PLANT IS IN OPERATION. THE EVIDENCE THAT ONLY TWO OF THE THREE FULES ARE CONNECTED SUGGESTS THAT THE PLANT IS OPERATING AT APPROXIMATELY TWO-THIRDS CAPACITY.

25X1

[REDACTED] REVEALS MAJOR EXTERIOR REPAIR TO THE NAM DINH TPP. PREVIOUSLY, ONLY MINOR ROOF REPAIR OR SHED CONSTRUCTION HAD BEEN OBSERVED AT ANY TPP. THE PHOTOGRAPHY REVEALS TWO OF THE FOUR HEAVILY DAMAGED COOLING TOWERS BEING REPAIRED (AND SMOKE EVIDENCES THEIR USE ALTHOUGH STILL IN A STAGE OF REPAIR), CONSTRUCTION OF A NEW COAL STORAGE AND PROCESSING BUILDING, CLEARING ACTIVITY, AND CONSTRUCTION OF A U/I STRUCTURE. REPAIRS TO THE BOILER HOUSE ROOF CONTINUE AND THE FLUE SYSTEM APPEARS INACTIVE. SMOKE IS OBSERVED EMANATING FROM BOTH THE OLD AND THE NEWER BOILER HOUSE.

25X1

25X1

These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing boards (s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue. For information concerning these notes contact Chief, Imagery Exploitation Group NPIC.

**CONFIDENTIAL**

25X1